


Firing Chart for Pearl[®] Screw-Retained Hybrid Bridges

Regular Firing Temperature for a Large Unit



For best results, ensure your sintering oven is calibrated properly and the firing program is followed accurately.





Partner With CMC

Comprehensive Treatment
Planning and Surgical
Guide Solutions

NOW AVAILABLE!



custom-milling.com • 877-933-6455